DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 08/07/2017 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		A. BUILDING	PLE CONSTRUCTION G 01, 02	(X3) DATE SURVEY COMPLETED	
		495213		B. WING	· · · · · · · · · · · · · · · · · · ·	06/22/2017	
	ROVIDER OR SUPPLIER	BILITATION CENTE			STATE, ZIP CODE ENCE BLVD	•	
DATSIDE	HEALIN & RENA	BILITATION CENTE			I, VA 23455		
(X4) ID PREFIX TAG	SUMMARY ST (EACH DEFICIENCY MUS' OR LSC IDE		ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE COMPLETION	1	
K 000	00 INITIAL COMMENTS			K 000			
	Description of structure: The facility is a one story masonry structure Type V (111). Sprinkler Status: Fully sprinklered - NFPA 13 An unannounced Standard Recertification Life Safety Code Survey was conducted on 06/22/17 in accordance with 42 Code of Federal Regulation, Part 483: Requirements for Long Term Care Facilities. The facility was surveyed for compliance using the LSC 2012 Existing regulations. The facility was not compliance with the Requirements for Participation Medicare and Medicaid.						
	Description of struc	ith Title 42 Code of Life Safety from Fire.) cture:The facility is 1 structure with a cons	struction				
	survey was conducted accordance with 42 Part 483: Requirent Facilities. The facilities compliance using the regulations. The facility according to the facility of the facilit	ecertification Life Safe cted 06/22/2017 in 2 Code of Federal Re- nents for Long Term 0 ility was surveyed for the LSC 2012 Existing acility was found to be e Requirements for care and Medicaid.	gulation, Care				
K 324 SS=E	NFPA 101 Cooking	y Facilities		K 324			
33=E	with NFPA 96, Star	nt is protected in acco ndard for Ventilation C n of Commercial Cook	Control				

(X2) MULTIPLE CONSTRUCTION

TITLE LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

(X6) DATE

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Printed: 08/07/2017 FORM APPROVED

CENTE	RS FOR MEDICARE	& MEDICAID SERV	ICES	OMB NO. 0938-0391									
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 , 02		(X3) DATE SURVEY COMPLETED							
		495213		B. WING		06/22/2017							
NAME OF I	PROVIDER OR SUPPLIER		STREET ADI	DRESS, CITY, S	STATE, ZIP CODE								
BAYSIDE HEALTH & REHABILITATION CENTE 1004 INDEPENDENCE BLVD													
VIRGINIA BEACH, VA 23455													
(X4) ID PREFIX TAG	(EACH DEFICIENCY MUST	TATEMENT OF DEFICIENCIE T BE PRECEDED BY FULL I ENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF ((EACH CORRECTIVE ACT) CROSS-REFERENCED TO T DEFICIENC	ION SHOULD BE HE APPROPRIATE	(X5) COMPLETION DATE						
K 324		-		K 324									
	Operations, unless		0										
		g equipment (i.e., sm s microwaves, hot pla											
		for food warming or I											
		nce with 18.3.2.5.2,											
		open to the corridor i 30 or fewer patients											
		under 18.3.2.5.3, 19											
	or * cooking facilities in smoke compartments with												
	30 or fewer patients comply with conditions under 18.3.2.5.4, 19.3.2.5.4. Cooking facilities protected according to NFPA 96 per 9.2.3 are not required to be enclosed as												
	hazardous areas, b	out shall not be open	to the										
		18.3.2.5.4, 19.3.2.5.	I through										
	19.3.2.5.5, 9.2.3, T		3										
		ot met as evidenced											
	•	vation the kitchen hoo n is not being proper											
	Findings include												
	Findings include												

Maintenance Director.

door.

SS=D Smoke Barrie

Doors

On 22 Jun 2017 at 10:20 AM, it is observed that the pull station for the kitchen hood suppression system is blocked from view by the entrance

The above deficiencies were observed by the

Subdivision of Building Spaces - Smoke Barrier

K 374 NFPA 101 Subdivision of Building Spaces -

K 374

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 08/07/2017 FORM APPROVED OMB NO. 0938-0391

(X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING **01, 02** COMPLETED 495213 B. WING 06/22/2017 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER **BAYSIDE HEALTH & REHABILITATION CENTE** 1004 INDEPENDENCE BLVD VIRGINIA BEACH, VA 23455 PROVIDER'S PLAN OF CORRECTION (X5) COMPLETION SUMMARY STATEMENT OF DEFICIENCIES (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY PRÉFIX **PREFIX** (EACH CORRECTIVE ACTION SHOULD BE DATE TAG OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) K 374 Continued From page 2 K 374 2012 EXISTING Doors in smoke barriers are 1-3/4-inch thick solid bonded wood-core doors or of construction that resists fire for 20 minutes. Nonrated protective plates of unlimited height are permitted. Doors are permitted to have fixed fire window assemblies per 8.5. Doors are self-closing or automatic-closing, do not require latching, and are not required to swing in the direction of egress travel. Door opening provides a minimum clear width of 32 inches for swinging or horizontal doors. 19.3.7.6. 19.3.7.8. 19.3.7.9 This Standard is not met as evidenced by: Based upon observations the fire rated smoke barrier walls have penetrations, joints and openings that are not fire stopped and could allow smoke to pass from one side of the smoke barrier to the other side. Findings include On 22 Jun 2017 at 1115 AM, it is observed that there is an open penetration above the ceiling at the smoke doors next to physical therapy. On 22 Jun 2017 at 1127 AM, it is observed that there is an open penetration above the ceiling at the smoke doors near room 24. The above deficiencies were observed by the Maintenance Director.